



# EIGHT CIRCUIT TRIAC DRIVER BOX



Warning  
 50 riding out  
 115  
 Do not use Ground  
 for Testing.




Replacement  
 opto must be  
 Darlington output.


990-5

CC - SP	/	CONTROLLED SPOT LIGHTS
CC - CL	/	CONTROLLED CEILING FLOODS - S.L.
CC - HL	/	CONTROLLED HOUSE LIGHTS
CC - CS	/	CONTROLLED CEILING FLOODS - C.S./S.I.


1/4 watt ack's like a fuse.



20 TRIAC DRIVER BOARD



20 TRIAC DRIVER BOARD



8 TRIAC DRIVER BOARD

TITLE: TRIAC DRIVER BOARDS

DRAWN BY: *Gowshud Khesiyam*

DATE: 8/8/95